

10053790.052002




FIG. 1

200507062500




FIG. 2

200250-0625002




FIG. 3




FIG. 4





FIG. 5

FIG. 6



200250" 0622500F

FIG. 7






FIG. 8



10053790.052002



FIG. 9



10053790.0625007

FIG. 10





FIG. 11

200250 062500

FIG 12






FIG 13



1052790-0625001

FIG 14



SCHEMATIC LAYOUT OF MOTOR CONTROL ENCLOSURE